

**SB SERVICE di STEFANO BARLETTA**

VIA F. SEVERI, 8
70023 CASTELLANA GROTTA (BA)
TELEFONO 080/4031660 - 329/2928590

website www.sbricambi.it

Costruttore	Modello	Tipo	Anno [da]	Anno [a]	kW	HP	cc	Cil.	Val.	Mot ore	Nr. tipo TecDoc
-------------	---------	------	--------------	-------------	----	----	----	------	------	------------	--------------------

Ford	Fiesta V (JH_, JD_)	1.4 TDCi	2001-11	2008-6	50	68	1399	4	2	F6JA	16102
Ford	Fiesta V (JH_, JD_)	1.4 TDCi	2001-11	2008-6	50	68	1399	4	2	F6JB	16102
Ford	Fiesta V Van	1.4 TDCi	2003-10	2010-12	50	68	1399	4	2	F6JA	26670
Ford	Fiesta V Van	1.4 TDCi	2003-10	2010-12	50	68	1399	4	2	F6JB	26670
Ford	Fusion (JU_)	1.4 TDCi	2002-8	2012-12	50	68	1399	4	2	F6JA	16626
Ford	Fusion (JU_)	1.4 TDCi	2002-8	2012-12	50	68	1399	4	2	F6JB	16626
Mazda	2 (DY)	1.4 CD	2003-4	2007-6	50	68	1399	4	2	F6JA	17318
Mazda	2 (DY)	1.4 CD	2003-4	2007-6	50	68	1399	4	2	F6JB	17318